

SURVEY OF THE WEST BOUNDARY OF T. 32 N., R. 31 E.

Chains

ground, for  $\frac{1}{4}$  sec. cor., with brass cap mkd.;

$\frac{1}{4}$  S 36 | S 31  
1912;

dig pits, 18x18x12 ins., N. and S. of post, 3 ft. dist.; and raise a mound of earth,  $3\frac{1}{2}$  ft. base,  $1\frac{1}{2}$  ft. high, W. of cor.

52.60 Main dry wash, 40 lks. wide; course S.E.

63.60 Road, bears N.W. and S.E.

80.00 Intersect the cor. of Ts. 31 and 32 N.; Rs. 30 and 31 E., heretofore described.

Land gently rolling.

Soil, sandy; 3rd. rate.

No timber; desert brush.

September 2, 1912.

RESURVEY OF THE NORTH BOUNDARY OF T. 32 N., R. 31 E.

Sept. 17, 1912:- At 9h. 00m. a.m., l.m.t., I set off  $40^{\circ}40'N.$  on the lat. arc;  $2^{\circ}14\frac{1}{2}'N.$  on the decl. arc; and determine a meridian with the solar at the cor. of T. 32 N., Rs. 30 and 31 E., heretofore described; thence, I retrace E. along N. bdy. of T. 32 N., R. 31 E. At 38.76 chs., after diligent search, I failed to find any trace of old  $\frac{1}{4}$  sec. cor. I continue retracement line east, and failed, after two days diligent search, to find any trace of any of the  $\frac{1}{4}$  sec. or sec. cors. on the N. bdy. of the township. At 478.76 chs., I failed after one days diligent search, to find any evidence of the old cor. of Ts. 32 and 33 N., Rs. 31 and 32 E. At this point, I therefore set a temp. cor. of said Ts. 32 and 33 N. Rs. 31 and 32 E.

To re-establish this corner I proceeded as follows:-  
Knowing the position and existence of the cor. of secs. 5, 6, 31 and 32, on N. bdy. of T. 32 N., R. 33 E., I retrace due west from said cor. finding distinct evidence of several  $\frac{1}{4}$  sec. and sec. cors. along the N. bdy. of T. 32 N., R. 32 E. At a point about 6