

Retracement of E. Bdy. of T31N, R37E

Chains

Thence I retrace North bet. secs. 1 and 6. at 40.00 chs., I find no trace of $\frac{1}{4}$ sec. cor. after careful search, I continue N. on same line and at 80.04 chs., intersect the cor. of Tps. 31 and 32 N, R 37 and 38 E, which is an iron post heretofore described.

July - 15 - 1913.

From the ^{S.E.} cor. of T₃₁N, R₃₇ and 38 E. on S Bdy of T31N, R37E. Lat. 40°30' N.
Long. 117°45' W.
Mag. Decl. 19°17' E.
I retrace W. Sixth Standard Parallel North, at 40.00 and 80.00 chs. I find no trace of $\frac{1}{4}$ sec. cor. and sec. cor. I build temp. points and continue W. on same line. and find no trace of standard cor. until 318.16 chs.; fall 5.04 chs N. of standard cor. of sec. 32 and 33 which is a juniper stake 3x3x30 ins. built in mound of stone and marked as described by the surveyor general, the line bears N 87°06' E.; the length of each mile will be 79.54 chs, and the correction is 63 chs S. for each half mile.

July - 14 - 1913

Resurvey of E. Bdy. of T31N, R37E

From cor. of Tps. 31 and 32 N, R₃₇ and 38 E, which is an iron post heretofore described,
I resurvey South on a true line bet. secs. 1 and 6