

Chains.

N. bet. secs. 7 and 12

Over level barren desert

17.90 Wash, course S.W.

22.45 Wash, course S.W.

40.00 Set an iron post 3 ft. long, 1 in. diam 24 ins. in the ground for $\frac{1}{4}$ sec cor. with brass cap mkd.

$$\begin{array}{r} S12\frac{1}{4} \quad | \quad S7 \quad \checkmark \\ \hline 1912 \end{array}$$

dig pits 18x12x12 ins. N. and S. of post 3 ft. dist. and raise a mound of earth 3 $\frac{1}{2}$ ft. base, 1 $\frac{1}{2}$ ft. high W. of cor.

80.00 Set an iron post 3 ft. long, 3 ins diam. 24 ins. in the ground for cor. of secs. 1, 6, 7 and 12, with brass cap mkd.

$$\begin{array}{ccc} & T30N & \\ & R20E & R21E \\ S1 & | & S6 \quad \checkmark \\ \hline S12 & | & S7 \\ & & 1912 \end{array}$$

dig pits 18x18x12 ins. in each sec. 5 $\frac{1}{2}$ ft. dist. and raise a mound of earth 4 ft. base, 2 ft. high W. of cor. Land level, barren desert.

Soil, adobe, full of alkali and other salts. 4th. rate, unfit for cultivation. No vegetation, slight S.W. slope

N. bet. secs. 1 and 6

Over level, barren desert.

1.20 Wash, course W.

40.00 Set an iron post 3 ft. long, 1 in. diam 24 ins. in the ground for $\frac{1}{4}$ sec cor with brass cap mkd.

$$\begin{array}{r} S1\frac{1}{4} \quad | \quad S6 \\ \hline 1912 \end{array}$$

dig pits 18x18x12 ins. N. and S. of post