

Resurvey of the old California-Nevada State Line

11

Chains

Owing to the poor condition of the old cor. of Tps. 18 and 19 N., Rs. 18 E. Cal. and Nev. I reestablish this cor. as follows:

Set an iron post, 3 ft. long, 3 ins. in dia., 16 ins. in the ground to solid rock and 8 ins. in a mound of stone, for cor. of Tps. 18 and 19 N., Rs. 18 E. with brass cap mkd.

T19N
R18E | R18E
S31 | S31
S5 | S6
T18N
1918

From which

A cedar, 20 ins. dia., bears N. 8° 00' E., 36 lks. dist., mkd. T 19 N R 18 E S 31 B T.

A pine, 18 ins. dia., bears S. 56° 20' E., 1.24 chs. dist., mkd. T 18 N R. 18 E S 6 B T.

A cedar, 32 ins. dia., bears S. 11° 05' W., 1.36 chs. dist., mkd. T 18 N R 18 E S 6 B T.

A pine, 30 ins. dia., bears N. 78° 30' W., 57 lks. dist., mkd. T 19 N R 18 E S 31 B T.

Thence on a dependent resurvey, N. 0° 16' W., bet. secs. 31 and 31.

Over rough broken mountainous land, Asc. steep SE. slope, through dense undergrowth and scattering timber, surface covered with slide rock and many outcrops.

9.00 Point of rocky spur, 305 ft. above sec. cor., projects SE.; desc.

18.60 Head of ravine, course E.; asc. abruptly.

30.40 Top of spur ridge, 190 ft. above ravine, bears E. and W.; desc. N. slope.

40.28 The old $\frac{1}{4}$ cor. of secs. 31 and 31, previously described.

I reestablish this cor. at the same point as follows:

Set an iron post, 3 ft. long, 1 in. in dia., 24 ins. in the ground, for $\frac{1}{4}$ sec. cor., with brass cap mkd.

$\frac{1}{4}$
S31 | S31
1918