

20.

Survey of Subdivisions of T. 33 N., R. 52 E.

Chains and raise a mound of stone, 2 ft. base, $1\frac{1}{2}$ ft. high E. of corner.
 Land; rolling mountains.
 Soil; rocky clay loam, 3rd. rate, subsoil same.
 No timber.
 Undergrowth; dense sage brush.
 Drainage, S.
 Ruban W. Riley

U.S. Transitman Aug. 8, 1914.

BOUNDARIES OF T. 33 N., R. 52 EAST

Latitudes, Departures and Closing Errors.					
Line Designated	True Bearing	Distance	Latitudes N. to S.	Departures E. to W.	
South Bdy.	N. $89^{\circ}31'W$	80.96	.68		80.96
West Bdy.	N. $0^{\circ}9'W$	80.59	80.59		.21
West Bdy.	N. $0^{\circ}7'E$	80.69	80.69		
West Bdy.	N. $0^{\circ}2'W$	80.69	80.69		.05
West Bdy.	N. $0^{\circ}15'W$	80.53	80.53		.35
West Bdy.	N. $0^{\circ}6'W$	80.53	80.53		.14
West Bdy.	N. $0^{\circ}4'E$	79.28	79.28		.10
North Bdy.	N. $89^{\circ}57'E$	80.89	.07	80.89	
S. on the E.Bdy. Sec. 6	S. $4^{\circ}31'W$	43.69	43.55		3.43
S. on the E.Bdy. Sec. 6	S. $0^{\circ}36'E$	39.98	39.98		.42
S. on the E.Bdy. Sec. 7	S. $0^{\circ}34'E$				
S. on the E.Bdy. Sec. 18	S. $0^{\circ}34'E$				
S. on the E.Bdy. Sec. 19	S. $0^{\circ}34'E$				
S. on the E.Bdy. Sec. 30	S. $0^{\circ}34'E$				
S. on the E.Bdy. Sec. 31	S. $0^{\circ}34'E$	399.50	399.48		3.94
Convergency					.10
Totals-----		483.06	483.01	85.51	85.24
		483.01		85.24	

Error in Latitude----- .05
 Error in Departure----- .27

GENERAL DESCRIPTION.

This fraction of tp. contains rolling land and the soil ranges from a rocky clay loam to yellowish-gray, gravelly loam, not suitable for producing crops without irrigation. The soil could be classed as 2nd. rate in this fraction. There is an abundant growth of sage brush, and of a rich nutritious grass good for grazing purposes. There is no water in this fraction, which makes it very arid.

There are no settlers on this fraction at the present. The value of the land is principally for grazing purposes.

I find no indications of mineral in the tp.

Scott P. Stewart,

U. S. Surveyor.

Ruban W. Riley,

U.S. Transitman