

Latitudes, Departures and Closing Errors.

Line Designated	True Bearing	Distance.	Latitude		Departure	
			N.	S.	E.	W.
W.Bdy.of Tp.	S.0°10'E.	98.62		98.62	.28	
	N.89°25'E	64.12	.65		64.12	
S.Bdy.of Tp.	N.88°17'E	159.32	4.78		159.24	
	S.89°55'E	256.95		.37	256.95	
E.Bdy.of Tp.	North	94.43	94.43			
N.Bdy.sec.36	West	80.00				80.00
E.Bdy.sec.26	North	80.00	80.00			
N.Bdy.sec.26	West	80.00				80.00
E.Bdy.sec.15-22	North	160.00	160.00			
N.Bdy.sec.15-16	West	160.00				160.00
W.Bdy.sec.16-21	South	160.00		160.00		
N.Bdy.sec.29	West	80.00				80.00
W.Bdy.sec.29	South	80.00		80.00		
N.Bdy.sec.31	N.89°37'W	80.49	.54			80.49
Convergency						.25
			340.40	338.99	480.59	480.74
			338.99			480.59
Error in lat.			1.41	Error in dep.		0.15

GENERAL DESCRIPTION.

This fractional township consists almost wholly of high, rolling to rough mountains of quartz pebble conglomerate rocks, and volcanic rocks. Sections 31 and 32 are mostly of volcanic rock while the rest is mostly quartz pebble conglomerate.

The quartz pebble conglomerate part is made up largely of high, rounding hills and deep ravines, all plentifully covered with gravel from the decomposition of the conglomerate. It is a very fair grazing country, there being a good growth of sagebrush, with considerable grass, weeds and other feed. It is sufficiently well watered for grazing. There is no land suitable for cultivation, it all being too dry, gravelly, steep and rocky. Also there is no water for irrigation, and without irrigation very little can be done in this country in the way of farming. There is no timber, settlers or land in cultivation.

Sept. 13, 1915.

Winfred A. Pray
U.S. Surveyor.

Note:

Where stones were used for corners instead of iron posts, it was done because I had no iron posts available at the time.