



Resurvey of fractional S. bdy. T 24 N, R 23 E.

Chains
 Begin at the closing corner of Tps. 23 and 24 N, R 23 E, on the bdy. of the Pyramid Lake Indian Reservation. Corner previously described.
 Thence S 89°53'E, south of sec. 35.
 Descending S.E. slope of sandy ridge.
 9.90 Slope changes to steeper E. slope, 90 ft. below closing corner. Desc. E. slope.
 18.15 Old closing corner of secs. 1 and 2, previously described. Reestablish this corner as follows:
 At the same point, set an iron post, 3 ft. long, 2 ins. dia 24 ins. in the ground for closing corner of secs. 1 and 2, with brass cap mkd.



Repair the accessories of the old cor., and set the old cor. alongside of post. *Dist. 5 ft. N. side of post.*
 22.40 N.W. bank of slough, flows N 15°E, 105 ft. below change of slope. Thence across slough, 3 ft. deep.
 22.89 S.E. bank of slough. Asc. gradually.
 25.90 Low ridge, bears N 15°E and S 15°W, 15 ft. above slough. Desc. gradually.
 29.69 Old cor. of secs. 35 and 36, previously described. Reestablish this cor. as follows;
 At the same point, set an iron post, 3 ft. long, 2 ins. dia 24 ins. in the ground for cor. of secs. 35 and 36, with brass cap mkd.



1916

dig pits, 24 x 24 x 12 ins. in each sec., 6 ft. dist. and set old cor. alongside of post.
 Land; west of slough is rolling, sandy ridges; and east of slough is level bottom land; sandy ridges are 2nd. rate and bottom land is 1st. rate.
 Soil, sandy loam, good quality in bottom. Rather poor feed