Dependent Resurvey of a portion of the S. Rdy. of T. 37 N., R. 18 E.

N. 89° 21' W., on a true line on the S. Bdy. of sec. 35. Over level land, through dense undergrowth. Along wire fence and road paralleling line.

34.64

Set an iron post, 3 ft. long, 1 in. diam., 25 ins. in the ground, for $\frac{1}{4}$ cor. of sec. 2, with brass cap mkd.

4 S 2 /

dig pits, 18x18x12 ins. E. and W. of cor., 3 ft. dist. $40.30\frac{1}{2}$ Proportionate distance for the $\frac{1}{4}$ cor., of sec. 35, which is also a line point for Tract No. 49, at which point, Set an iron post, 3 ft. long, 1 in. diam., 26 ins. in the ground, for $\frac{1}{4}$ cor. of sec. 35, and line point for Tract No. 49, with brass cap mkd.

1 S 35 LP TR49

74:64

dig pits, 18x18x12 ins. E. and W. of cor. 3 ft. dist. Set an iron post, 3 ft. long, 2 ins. diam., 24 ins. in the ground, for cor. of secs. 2 and 3, with brass cap mkd.

. S3 | S2 T36N | R18E

dig pits, 24x24x12 ins. in each sec. SE. and SW. of cor. . 6 ft. dist.

-80.61

Intersect the old cor. of secs. 2, 3, 34 and 35, which is a cottonwood post, la ins. sq., 2 ft. long, broken off with markings nearly obliterated, lying alongside of traces of old mound of earth, with a pine stake 6 ft. long, in the center. This cor. is identical with cor. No. 3 of Tract No. 49 and cor. No. 1 of Tract No. 51. As this cor. is in poor condition, I reestablish this cor. in its original position as follows:

Set an iron post, 3 ft. long, 2 ins. diam., 24 ins. in the ground, for cor. of secs. 34 and 35, and cor. No. 3 of Tract No. 49 and cor. No. 1 of Tract No. 51, with brass cap mkd.

> T37N |R18E S34 |S35 3AP TR51 | TR49