chains

29 E., with brass cap mkd:

T 352 N

dig pits, 18x18x12 ins., N., E., S. and W. of cor., 3 ft. dist.

Land, level.

Soil, sandy clay, 3rd rate.

Undergrowth, greasewood, salt sage.

From the cor. of  $\P$ s. 35 and  $35\frac{1}{2}$  N., Rs. 28 and 29 E., North, on true line,

Over level desert land thru scattering undergrowth.

Drain, 3 ft. wide, 1 ft. deep, course SE.

Set an iron post, 3 ft. long, 1 in. diam., 26 ins. in the ground, for \frac{1}{2} see. cor. of secs. 3 land 36, with brass cap mkd:

80.00

6.25

40.00

dig pits, 18x18x12 ins., N. and S. of cor., 3.ft.dist
Set an iron post, 3 ft. long, 2 ins. diam., 24 ins. in
the ground, for cor. of secs. 25, 30, 31 and 36, with
brass cap mkd:

dig pits, 18x18x12 ins., in each sec., 3 ft. dist. Land, level.

Soil, sandy clay, 3rd rate. Undergrowth, greasewood.