

## SURVEY OF SUBDIVISIONS OF T. 24 N., R. 45 E.

CHAINS	N 0° 01' W., on a random line bet. secs. 5 and 6
40.00	Set temp $\frac{1}{4}$ sec. cor. S. 89° 59' W.
79.90	Fall 2 lks. $\frac{1}{4}$ of the cor. of secs. 5; 6, 31 and 32, on N. bdy. of the twp., hereinbefore described
	Thence
	South, on true line bet. secs. 5 and 6
	Over nearly level land
33.40	Dry wash, drains NW.
39.90	Set an iron post, 3 ft. long, 1 in. in dia., 26 ins. in the ground, for $\frac{1}{4}$ sec. cor., with brass cap marked
	$\frac{1}{4}$
	S6 S5
	1922
	Dig pits crosswise on line, N. and S. of cor.
79.90	The cor. of secs. 5, 6, 7 and 8
	Land, nearly level. Soil, sandy. Timber, none.
	Undergrowth, sage and shadscale. General drainage, NW.

## LATITUDES, DEPARTURES AND CLOSING ERRORS.

Lines designated	True bearings	Dist- ances Chs	Latitudes		Departures	
			N Chs	S Chs	E Chs	W Chs
E. boundary	South	480.00		480.00		
S. boundary	N 89° 56' W	478.22	.57 ✓			478.22
W. boundary	North	480.00	480.00			
N. boundary	N 89° 59' E	477.64	.14 ✓		477.64	
Convergency					.61	
			480.71	480.00	478.25	478.22
			480.00		478.22	
Error in latitude.....			.71			
Error in departure.....					.03	

GENERAL DESCRIPTION.

The east range of sections and portions of sections 26, 34 and 35 of this township are rolling mountainous in character. All of the remaining sections are level to gently rolling, and could be put under cultivation, if sufficient water could be obtained for irrigation purposes. Portions of the SW $\frac{1}{4}$  of section 33, SE $\frac{1}{4}$  of section 32, and NE $\frac{1}{4}$  of section 32 are the only areas under cultivation.