

Survey of E. Bdy. T. 20 N., R. 45 $\frac{1}{2}$ E.

CHAINS

80.00 Set an iron post, 3 ft. long, 2 ins. in dia., 6 ins. in rocky ground, in a mound of stone, for the cor. of secs. 7, 12, 13 and 18, with brass cap mkd

T20N
R45 $\frac{1}{2}$ E R46E
S12 S7
S13 S18

1924

At base of post deposit a marked(X) stone, 1x4x6 ins.

Land, rolling bench land. Timber, none.

Soil, gravelly loam. Undergrowth, sagebrush.

General drainage, NE. Fair grazing.

North bet. secs. 7 and 12

Over rolling land

40.00 Set an iron post, 3 ft. long, 1 in. in dia., 18 ins. in rocky ground, in a mound of stone, for the $\frac{1}{4}$ sec. cor., with brass cap mkd

$\frac{1}{4}$
S12 S7

1924

At base of post deposit a marked(X) stone, 2x4x4 ins.

Continue over rolling land

80.00 Set an iron post, 3 ft. long, 2 ins. in dia., 18 ins. in rocky ground, in a mound of stone, for the cor. of secs. 1, 6, 7 and 12, with brass cap mkd

T20N
R45 $\frac{1}{2}$ E R46E
S1 S6
S12 S7

1924

At base of post deposit a marked(X) stone, 2x2x5 ins.

Land, rolling. Timber, none. Undergrowth, sagebrush.

Soil, gravelly. Drainage, NE. Fair grazing.

North bet. secs. 1 and 6

Over rolling land

16.50 Draw, drains NE.

40.00 Set an iron post, 3 ft. long, 1 in. dia., 27 ins. in the ground, for $\frac{1}{4}$ sec. cor., with brass cap mkd