

Survey of the subdivisions of T. 15 N., R. 50 E.

Chains.
39.94

Set an iron post, 3 ft. long, 1 in. in diam., 27 insl in the ground, for the $\frac{1}{4}$ sec. cor., with brass cap mkd.

$$\begin{array}{r} S2 \\ \frac{1}{4} \\ \hline S11 \\ 1926 \end{array}$$

At base of post deposit a broken amber colored pint bottle.

58.10 Dim road, bears NE. and S. 80° W.

77.30 Road, Herrera ranch to Lincoln Highway, bears NE. and SW.

79.88 The cor. of secs. 2, 3, 10 and 11.

Land, nearly level. Soil, gravelly clay. Undergrowth, white sage; very scant growth of grass. No timber.

N. 0° 01' W., bet. secs. 2 and 3.

Desc. gradual NW. slope over nearly level land.

40.00 Set an iron post, 3 ft. long, 1 in. in diam., 27 ins. in the ground, for the $\frac{1}{4}$ sec. cor., with brass cap mkd.

$$\begin{array}{r} \frac{1}{4} \\ S3 \mid S2 \\ \hline 1926 \end{array}$$

At base of post deposit a granite stone, 8 x 6 x 3 ins., marked with cross (x). Pits impracticable and no other accessories available.

82.58 Intersect the Third Standard Parallel North, at a point, East, 5.90 chs. distant, from the standard cor. of secs. 34 and 35. At the point of intersection set an iron post, 3 ft. long, 2 ins. in diam., 27 ins. in the ground, for the closing cor. of secs. 2 and 3, with brass cap mkd.

$$\begin{array}{r} T16N R50E \\ \hline S35 \\ S3 \mid S2 \\ T15N R50E \\ C \mid C \\ 1926 \end{array}$$

At base of post deposit a granite stone, 10 x 7 x 8 ins., marked with cross (x). Pits impracticable and no other accessories available.

Land, nearly level; general NW. drainage. Soil, gravelly clay. Undergrowth, white sage and rabbit brush; very scant growth of grass.