

## DEPENDENT RESURVEY OF T. 17 N., R. 25 E.

## Chains

proportionate measurement. All missing  $\frac{1}{4}$  sec. cors. were restored by single proportionate measurement on line connecting the adjoining section corners.

All extant original corner monuments on the township exteriors and in the subdivision of the township, were reconstructed by placing the regulation iron post corner alongside the original corner.

## RETRACEMENT OF

## EAST BOUNDARY OF T. 17 N., R. 25 E.

## Random Lines.

From the cor. of Ts. 16 and 17 N., Rs. 25 and 26 E., hereinafter described.

Thence

North, on retracement line bet. secs. 31 and 36, along E. bdy. of Tp.

40.18 Fall 24 lks. E. of the  $\frac{1}{4}$  sec. cor., hereinafter described.

The course of this half mile therefore is N.  $0^{\circ} 21' W.$ , and the dist. is 40.18 chs.

From the  $\frac{1}{4}$  sec. cor.

North, on retracement line.

40.00 No evidence of the cor. of secs. 25, 30, 31 and 36 could be found.

80.30 Fall 12 lks. E. of the  $\frac{1}{4}$  sec. cor., bet. secs. 25 and 30, hereinafter described.

The course of the line from the  $\frac{1}{4}$  sec. cor. bet. secs. 31 and 36, to the  $\frac{1}{4}$  sec. cor. bet. secs. 25 and 30, therefore is N.  $0^{\circ} 05' W.$ , and the proportionate length of each half mile is 40.15 chs.

From the  $\frac{1}{4}$  sec. cor. bet. secs. 25 and 30; thence North, on retracement line.

39.94 Fall 31 lks. W. of the cor. of secs. 19, 24, 25 and 30, hereinafter described.

The course of the N. half mile bet. secs. 25 and 30,