

## SURVEY OF THE CENTER LINE IN RANGE 58 EAST.

Chains

Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the ground, over a broken glass memorial, for angle point, with brass cap marked

Dig pits, 18x18x12 ins., on line, 3 ft. dist.

-----

Thence

N.29°45'E., on true line, over reed and tule covered bottom land and over small grassy knolls.

88.40 Near south end of long irregular shaped grassy knoll, Set an iron post, 3 ft. long, 1 in. diam., 25 ins. in the ground, over a broken glass memorial, for angle point, with brass cap marked

Dig pits, 18x18x12 ins., on line, 3 ft. dist.

-----

Thence

N.38°45'E., on true line, over a series of small grassy knolls and bottom land covered with reeds and tule.

35.40 Set an iron post, 3 ft. long, 1 in. diam., 26 ins. in the ground, for angle point, with brass cap marked

Dig pits, 18x18x12 ins., on line, 3 ft. dist.

-----

Thence

N.24°30'E., on true line, over small grassy knolls and meadow land.

76.90 On SW. side of grassy elevation, set an iron post, 3 ft.