


SURVEY OF THE CENTER LINE IN RANGE 59 EAST

Chains

long, 1 in. diam., 26 ins. in the ground, for angle point, with brass cap marked




Dig pits, 18x18x12 ins., on line, 3 ft. dist.

Thence

N.14°30'E., on true line, over a series of low rolling grassy knolls and meadow land. Also, bottom lands of dark clay covered with weeds, reeds and tules.

95.80 Set an iron post, 3 ft. long, 1 in. diam., 26 ins. in the ground, over a broken glass memorial, for angle point, with brass cap marked




Dig pits, 18x18x12 ins., on line, 3 ft. dist.

Thence

N.50°45'E., on true line, over rolling grassy meadow land.

85.10 Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the ground, over a broken glass memorial, for angle point, with brass cap marked



Dig pits, 18x18x12 ins., on line, 3 ft. dist.

Thence

N.56°30'E., on true line, over rolling grassy meadow land.

36.00 Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the