

LATITUDES, DEPARTURES AND CLOSING ERRORS.

LATITUDES, DEPARTURES AND CLOSING ERRORS OF PORTION OF
LOT 3, SEC. 15, LYING EAST OF HIGHWAY RIGHT-OF-WAY AND
EXTENDING TO EAST BDY. SEC.15 AND MEANDER LINE OF LAKE.

Line designated	Course	Dist. chs.	Latitudes		Departures	
			N. chs.	S. chs.	E. chs.	W. chs.
N.bdy. lot 3	N.89°53'E	2.51	0.005		2.510	
Meanders, lot 3	S.41°00'E	3.26		2.460	2.139	
	S.32°45'E	8.25		6.938	4.464	
E.bdy. sec. 15	S.0° 04'W	5.92 $\frac{1}{2}$		5.925		0.007
Traverse, highway	N.2° 56'W	1.56	1.558			0.080
	N.8° 56'W	1.56	1.541			.242
	N.14°56'W	1.56	1.507			.402
	N.20°56'W	1.56	1.457			.557
	N.23°56'W	3.00	2.742			1.217
	N.28°42.5'W	1.59	1.394			.764
	N.38°15.5'W	1.59	1.248			.984
	N.47°48.5'W	1.59	1.068			1.178
	N.52° 35'W.	4.63	2.813			3.677
			15.333	15.323	9.113	9.108
			15.323		9.108	
Error in latitude and departure			.010		.005	

LATITUDES, DEPARTURES AND CLOSING ERRORS

NE. $\frac{1}{4}$ of SEC. 15.

Line designated	Course	Dist. chs.	Latitudes		Departures	
			N. chs.	S. chs.	E. chs.	W. chs.
W.bdy. NE. $\frac{1}{4}$ sec. 15	North	39.92	39.920			
N.bdy. NE. $\frac{1}{4}$ sec. 15	N.89°54'E	14.80	.026		14.80	
Meander, sec. 15	S.19°30'E	8.16		7.692	2.724	
	S.62°15'E	8.90		4.142	7.876	
	S.71°15'E	5.65		1.816	5.350	
	S.7° 45'E	3.70		3.666	.500	
	S.41°00'E	6.70		5.056	4.395	
	S.32°45'E	8.25		6.938	4.464	
E.bdy. sec. 15	S.0° 04'W	10.50		10.500		0.020
S.bdy. NE. $\frac{1}{4}$ sec. 15	S.89°52'W	40.13		.093		40.130
Totals			39.946	39.903	40.109	40.150
Error in latitude and departure			39.903		40.109	40.109
			0.043			0.041

GENERAL DESCRIPTION.

In compliance with special instructions for surveys under Group No. 128, Nevada, dated April 4, 1925, this survey was made to segregate that portion of land in lot 3, sec. 15, T. 24 N., R. 21 E., Nevada, lying east of the right-of-way of the main highway