

562

INDEPENDENT RESURVEY OF PORTION OF SUBDIVISIONS OF
T. 20 N., R. 53 E.

Chains	18x18x12 ins., N. and S. of post, 3 ft. dist. dig pits, Find no trace of original $\frac{1}{4}$ sec. cor. Deposit glass bottle at base of post.
48.00	Thence, over rolling land. Asc. sandy SE. slope 15 ft. to closing cor.
80.00	Set an iron post, 3 ft. long, 1 in. in dia., 27 ins. in the ground, for the cor. of lots 12 and 13 of sec. 4, and lots 9 and 16 of sec. 5, with brass cap mkd. S5 9 12 S4 16 13 1933
95.32	Deposit glass bottle at base of post. Intersect 4th stan. parallel north, which was resurveyed as the S. bdy. of T. 21 N., R. 53 E. in conjunction with the survey of this township, East 9.22 chs. from the stan. cor. of secs. 32 and 33, and is described in Book "B" of field notes under Group No. 133, and at point of intersection. Set an iron post, 3 ft. long, 2 ins. in dia., 27 ins. in the ground, for the closing cor. of secs. 4 and 5, with brass cap mkd. T21NR53E S 33 S5 S4 T20NR53E 30 1933
	18x18x12 ins., E., S., and W. of post, 3 ft. dist. dig pits, Deposit glass bottle at base of post. Land, gently rolling 48.00 chs.; rolling 47.32 chs. Soil, sandy and gravelly, 2nd rate. Timber, none. Undergrowth, sagebrush. General drainage, SE. Grazing, poor.

DEPENDENT RESURVEY OF PORTION OF SUBDIVISIONS OF
T. 20 N., R. 53 E.

REESTABLISHMENT OF THE SURVEYS EXECUTED BY E. L. BRIDGES
AND J. W. EATON, U. S. DEPUTY SURVEYORS IN 1872.

Random lines.

	From the cor. of secs. 31 and 32, on S. bdy. of township. North bet. secs. 31 and 32.
40.00	Find no trace of original $\frac{1}{4}$ sec. cor.
80.00	Find no trace of original sec. cor., set temp. point for the cor. of secs. 29, 30, 31, and 32. Thence on same line with continuous measurement bet. sec. 29 and 30.
120.00	Find no trace of original $\frac{1}{4}$ sec. cor.
160.00	Find no trace of original sec. cor., set temp. point for the cor. of secs. 19, 20, 29, and 30.