

## SUBDIVISIONS T. 111 N. R. 33 E.

Chains	No stone available for mound; pits impracticable
67.25	At base of post deposit a mkd(X) granite stone, 6x4x4 ins. Intersect N. bdy. of twp., 11.87 chs. W. of the original cor. of secs. 1, 2, 35 and 36, which is a 2 in. iron post, firmly set in the ground, properly mkd and witnessed. I remark same to read  T12NR33E  S35 S36  S1 T11NR33E  1931  Raise a mound of stone, 2 ft. base, $1\frac{1}{2}$ ft. high, N. of cor. At point of intersection the cor. to be filled. Set an iron post, 23 ifts. long, 27 inss. dia. by 27 ins. in the ground; for the closing cor. of secs. 1 and 2, with brass cap mkd T12NR33E  S35 S2 S1  T11NR33E CC 1931  Raise a mound of stone, 2 ft. base, $1\frac{1}{2}$ ft. high, S. of cor. Land, practically level to rolling. Timber, none. Soil, heavy sandy loam, 3rd rate. Undergrowth, sage, rabbit brush, greasewood. General drainage, NW. Grazing, poor. From the standard cor. of secs. 34 and 35, on S. bdy. of twp. N. 0° 01' W., between secs. 34 and 35 Over rough mountainous land through medium undergrowth Desc. steep rocky NW. slope 25 ft. to 1.45 Desc. steep rocky N. slope 25 ft. to 5.30 Desc. rocky NW. slope 165 ft. to