

DEPENDENT RESURVEY OF PORTION OF W. BOUNDARY T.8 N., R.46 E.

Chains

Undergrowth, sagebrush, yellow top.

General drainage, E. Grazing, fair.

DEPENDENT RESURVEY OF PORTION OF SUBDIVISIONS T.8 N., R.46 E.

REESTABLISHMENT OF SURVEYS EXECUTED BY DON H. BARKER,
U. S. DEPUTY SURVEYOR IN 1874.

Random lines.

From the cor. of secs. 1, 6, 7, and 12, on W. bdy. of tp.
East, bet. secs. 6 and 7.38.26 Find no trace of the original $\frac{1}{4}$ sec. cor.79.87 Fall 1.49 chs. N. of the original sec. cor., hereinafter
described.The bearing of this mile is S. $88^{\circ} 56'$ E., and the dist.
79.88 chs.

From the cor. of secs. 5, 6, 7, and 8

South, bet. secs. 7 and 8.

39.47 Fall 66 lks. E. of the $\frac{1}{4}$ sec. cor., hereinafter described.The bearing of this half mile is S. $0^{\circ} 57'$ W., and the
dist., 39.47 chs.From the $\frac{1}{4}$ sec. cor.

South, with continuous measurement.

78.74 Fall 71 lks. E. of the original cor. of secs. 7, 8, 17,
and 18, hereinafter described.The bearing of this half mile is S. $1^{\circ} 02'$ W., and the
dist., 39.28 chs.

From the cor. of secs. 7, 8, 17, and 18

West, bet. secs. 7 and 18.

40.00 No trace of the original $\frac{1}{4}$ sec. cor. found.

From the cor. of secs. 7, 8, 17, and 18

South, bet. secs. 17 and 18.

39.22 Fall 65 lks. E. of the $\frac{1}{4}$ sec. cor., hereinafter described.The bearing of this half mile is S. $0^{\circ} 56'$ W., and the
dist., 39.22 chs.From the $\frac{1}{4}$ sec. cor.

South, with continuous measurement

78.43 Fall 65 lks. E. of the original cor. of secs. 17, 18, 19,
and 20, hereinafter described.The bearing of this half mile is S. $0^{\circ} 56'$ W., and the
dist., 39.21 chs.