Chains 40.00	Set an iron post, 3 ft. long; l in. diam., 30 ins. in the ground, for the 4 sec. cor., with brass cap mkd.
	-s 4 s 3
	1936
	Deposit charcoal at base of post.
	Continue over gentle NE. slope.
57.60	Main road bears N.15°W. to Rawhide and Deadhorse Well, and S.15°E. to Luning.
65.90	Center of wash draining N.70°E.
577.5550	re reaction and make meeting and the substitute of the substitute
68.34	Intersect N. bdy. of the Tp.
	Set an iron post, 3 ft. long, 2 ins. diam., 30 ins. in the ground, for the closing cor. of secs. 3 and 4, Tp. 11 N., R. 32 E., with brass cap mkd.
	T12N R32E
	S34 S 3 T11N CCC 1936
	of stone, 4 ft. base, 3 ft. high, W. of cor.
	From point of intersection, the cor. of secs. 33 and 34, Tp. 12 N., R. 32 E., an iron post, 2 ins. diam., mkd and witnessed as described in the official record, bears West, 4.06 chs. dist.
	Land, gentle NE. slope, rolling. Soil, sandy; 3rd rate. Undergrowth, sage. Timber, none. Grazing, poor.
H 100	
	From the cor. of secs. 28, 29, 32, and 33, heretofore described.
1 7 1	N.0°03'W., bet. secs. 28 and 29
	Over rough rolling hills, thru medium dense scrub under- growth. Desc. 30 ft. over NW. slope.
.90	Draw drains N.60°E.; asc. 145 ft. over SE. slope.
12.50	Main spur projects N.30°E. from S.30°W.; desc. 210 ft. over NW. slope, to 27.30 ch. pt.
15.20	Head of draw draining N.30°W.
19.60	Spur projects N.60°W.
	Head of draw draining N.30°W. to junction.
23.00	nead of draw draining w. yo w. to June ton.