

ESTABLISHMENT OF THE $\frac{1}{4}$ SEC. COR. ON N. BDY. OF TP. 11 N., R. 32 E. 372

Chains	<p>QUARTER SEC. COR. ON N. BDY. OF SEC. 5.</p> <p>From the $\frac{1}{4}$ sec. cor. of sec. 32, Tp. 12 N., R. 32 E., East, 3.96 chs. dist.</p> <p>To a point mid-way bet. the closing cor. of secs. 4 and 5, and the closing cor. of secs. 5 and 6.</p> <p>Set an iron post, 3 ft. long, 1 in. diam., 30 ins. in the ground, for the $\frac{1}{4}$ sec. cor. of sec. 5 only, with brass cap mkd.</p> <p style="text-align: center;">$\frac{1}{4}$ S 5</p> <p style="text-align: center;">1936</p> <p>Deposit broken glass at base of post.</p>
	<p>QUARTER SEC. COR. ON N. BDY. OF SEC. 6.</p> <p>From the $\frac{1}{4}$ sec. cor. of sec. 31, Tp. 12 N., R. 32 E., East, 3.92 chs. dist.</p> <p>To a point 40.00 chs. West of the closing cor. of secs. 5 and 6.</p> <p>Set an iron post, 3 ft. long, 1 in. diam., 30 ins. in the ground, for the $\frac{1}{4}$ sec. cor. of sec. 6 only, with brass cap mkd.</p> <p style="text-align: center;">$\frac{1}{4}$ S 6</p> <p style="text-align: center;">1936</p> <p>Deposit broken glass at base of post.</p>
	<p>ESTABLISHMENT OF THE $\frac{1}{4}$ SEC. COR. ON W. BDY. OF TP. 11 N., R. 32 E.</p> <p>QUARTER SEC. COR. ON W. BDY. OF SEC. 31.</p> <p>From the standard cor. of Tps. 11 N., Rs. 31 and 32 E., North, 18.56 chs. dist.</p> <p>To a point 40.00 chs. South of the closing cor. of secs. 30 and 31.</p> <p>Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for the $\frac{1}{4}$ sec. cor. of sec. 31 only, with brass cap mkd.</p> <p style="text-align: center;">$\frac{1}{4}$ S 31</p> <p style="text-align: center;">1936</p> <p style="text-align: right;">raise a mound</p> <p>of stone, 2 ft. base, $1\frac{1}{2}$ ft. high, E. of cor.</p>
	<p>QUARTER SEC. COR. ON W. BDY. OF SEC. 30.</p> <p>From the cor. of secs. 25 and 36, Tp. 11 N., R. 31 E., North, 18.62 chs. dist.</p> <p>To a point mid-way bet. the closing cor. of secs. 30 and 31, and the closing cor. of secs. 19 and 30.</p>