

SUBDIVISION OF T. 9 S., R. 71 E.

Chains
40.00Point for the $\frac{1}{4}$ sec. cor. of secs. 3 and 4.Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 14 ins. in the ground and in a mound of stone to top, with brass cap mkd.
$$\begin{array}{c} \frac{1}{4} \\ S\ 4 \mid S\ 3 \\ 1953 \end{array}$$

Ascend 6 ft.

40.90 Long spur, slopes SE., desc. 320 ft. over NE. slope to Bull Valley.

60.00 Bull Valley channel, 80 lks. wide, between bluff walls, drains S. 30° E., asc. 335 ft. over SE. slope.

68.80 Side ravine, drains SE. for 10 chs. to another side ravine then SW. Ascend 130 ft.

79.48 The cor. of secs. 3, 4, 33 and 34, on N. bdy. of Tp.

Land, broken.

Soil, rocky.

Undergrowth, joshua, sagebrush, greasewood and cacti.

GENERAL DESCRIPTION

The land in Township 9 South, Range 71 East varies from nearly level gentle SE. slope thru rolling land cut by shallow to deep washes, broken hills, to rocky mountainous. The soil varies from coarse loam thru sand, gravel and rocks to bedrock. The undergrowth consists of sagebrush, greasewood and cacti and other desert growth, with joshua trees thruout the township. The quality of the grazing depends on seasonal precipitation which is normally low. There is no surface water in the township and no wells. There is no evidence of any mineral activity in the township.

A good scraped road, from Utah, bears west thru the south portion of secs. 10, 9 and 8, then NW. thru sec. 7 and leaves the township near the SW. cor. of sec. 6 heading for Snow Spring, about 1 mile distant.. Another improved road bears NW. thru portions of secs. 10, 9, 4 and 5, heading for a windmill in sec. 32 of T. 8 S., R. 71 E. Most of the washes can be traveled with 4-wheel drive equipment.