

ESTABLISHMENT OF THE ONE-QUARTER SECTION CORNERS ON THE  
NORTH BOUNDARY OF T. 44 N., R. 32 E.

Chains

ground, to bedrock and in a mound of stone to top, for the  $\frac{1}{4}$  sec. cor., for sec. 4, only, with brass cap marked

$\frac{1}{4}$  S 4

1936

of stone, 4 ft. base, 3 ft. high, S. of cor. raise a mound

Establishment of the  $\frac{1}{4}$  sec. cor. on the N. bdy. of sec. 5.

From the  $\frac{1}{4}$  sec. cor. for sec. 32, only, T. 45 N., R. 32 E., described on page 21, these notes.

West, along the N. bdy. of sec. 5, 5.67 chs. to a point which is equidistant (40.01 chs.) from the closing cors. of secs. 4 and 5, and 5 and 6. On an E. slope.

Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for the  $\frac{1}{4}$  sec. cor. for sec. 5, only, with brass cap marked

$\frac{1}{4}$  S 5

1936

of stone, 4 ft. base, 3 ft. high, S. of cor. raise a mound

Establishment of the  $\frac{1}{4}$  sec. cor. on the N. bdy. of sec. 6.

From the  $\frac{1}{4}$  sec. cor. for sec. 31 only, T. 45 N., R. 32 E., described on page 22, these notes.

West, along the N. bdy. of sec. 6, 5.68 chs. to a point which is West, 40.00 chs. dist. from the closing cor. of secs. 5 and 6. On W. slope.

Set an iron post, 3 ft. long, 1 in. diam., 30 ins. in the ground, for the  $\frac{1}{4}$  sec. cor. for sec. 6, only, with brass cap marked

$\frac{1}{4}$  S 6

1936

Deposit a volcanic stone, 4 x 4 x 3 ins., marked with a cross (X) at base of post.

ESTABLISHMENT OF ONE-QUARTER SECTION CORNERS ON THE  
WEST BOUNDARY OF T. 44 N., R. 32 E.

Establishment of the  $\frac{1}{4}$  sec. cor. on the W. bdy. of sec. 31.

From the  $\frac{1}{4}$  sec. cor. for sec. 36, only, T. 44 N., R. 31 E., described on page 11, these notes.