On the N. bdy. of Sec. 5.

Set an iron post, 3 ft. long, 1 in. diam., 8 ins. in the ground, to bedrock, with a lava stone, 6x5x4 ins., mkd. X deposited at base and in a mound of stone to top, for \(\frac{1}{4}\) sec. cor., with brass cap mkd.

From this corner, the following described corners;

The standard & sec. cor., an iron post, 1 in. diam., set, mkd., and witnessed as described in the official record, bears West 0.425 chs. dist.

The standard cor. of secs. 32 and 33, heretofore described bears East 39.575 chs. dist.

The closing cor. of secs. 4 and 5, heretofore described, bears East, 39.995 chs. dist.

The closing cor. of secs. 5 and 6, heretofore described, bears West, 39.995 chs. dist.

On the N. bdy. of sec. 6,

Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for $\frac{1}{4}$ sec. cor., with brass cap mkd.

raise a mound

of stone, 2 ft. base, 12 ft. high, S. of cor.

From this cor. the following described corners;

The standard t sec. cor. of sec. 31, an iron post 1 in. diam., set, mkd. and witnessed as described in the official record, bears West, 0.43 chs. dist.

The standard cor. of secs. 31 and 32, heretofore described bears East, 39.57 chs. dist.

The closing cor. of secs. 5 and 6, heretofore described bears. East, 40.00 chs. dist.

GENERAL DESCRIPTION

T. 45 N., R. 32 E., is located in the mountains West of Kings River about 100 miles North and West of Winnemucca, Nevada. Bilk Creek, a stream of good water flows through a canyon through the East half of the township. This township extends from Bilk Creek east to the top of the canyon and a short way down the slope of the Kings River, drainage to the west, the township extends over the mountain top west of Bilk Creek and across the broken hills drained by the dry channels known as Deep Creek and Texas Springs wash.

Although, apparently, badly overstocked the area is covered by a fair stand of native grasses, and brush, and has a very good supply of water for stock. Beside Bilk Creek water is obtained from Springs throughout the township as shown on the plat.

There is no settlement in the township and the only improvements consist of troughs at several of the springs.