Chains	for $\frac{1}{4}$ sec. cor. of sec. 7 only, with brass cap mkd.
	* s 7
•	1938 raise a mound
3	of stone, 3 ft. base; 1 ft. high, E. of cor.
80.00	Set an iron post, 3 ft. long, 2 ins. diam., 30 ins. in the ground, with a deposit of charcoal at base of post, for cor. of secs. 1 and 12 only, with brass cap mkd.
	T28N
	R25E R 26E
	$ \begin{array}{c c} & s & 1 \\ \hline & s & 12 \end{array} $ 1938
	S 12
	1938
	of stone, $2\frac{1}{2}$ ft. base, 2 ft. high, W. of cor.
600 10 10 10 10 10 100	Thus a manufacture to a grant of the same
	Land, gentle rolling. Soil, gravelly to fine rocky clay loam; 3d rate. Undergrowth, sagebrush, yellow top, rabbitbrush, white sage. Grazing, fair to good.
	North, along the E. bdy. of Sec. 1,
* *	Over nearly level land thru scattering undergrowth.
, , , ,	Set an iron post, 3 ft. long, 2 ins. diam., 30 ins. in the ground, with a deposit of broken glass at base of post and in a mound of stone, 3 ft. base, 8 ins. high, for cor. of secs. 6 and 7 only, with brass cap mkd.
	T28N
	R25E R26E
	s 1 s 6 x 7
	1938
37.40	Road, unimproved, bears N. 40° E. and S. 40° W.
40.00	Set an iron post, 3 ft. long, 1 in. diam., 30 ins. in the ground, with a deposit of charcoal at base of post, for \(\frac{1}{4}\) sec. cor., of sec. lonly, with brass cap mkd.
11,000	si
	1938
	raise a mound of stone, $2\frac{1}{2}$ ft. base, 1 ft. high, W. of cor.
, 11, 11, 11, 11, 11, 11, 11, 11, 11, 1	Set an iron post, 3 ft. long, 1 in. diam., '30 ins. in the ground, with a deposit of charcoal at base of post, for \(\frac{1}{2}\) sec. cor. of sec. 6 only, with brass cap mkd.
	‡ s 6
	s 6
	1938 dig pits.