

## WEST BDY. T. 30 N., R. 26 E., M.D.M.

Chains  
80.00

Point for the cor. of secs. 7, 12, 13 and 18.

Set an iron post, 3 ft. long, 2 ins. diam., 30 ins. in the ground, with brass cap mkd.

T30N	
R25E	R26E
S12	S7
S13	S18

1938

deposit a quart of charcoal at the base of the iron post.

Land, nearly level.

Soil, sandy and gravelly; 3rd rate.

Undergrowth, shadscale.

North, bet. secs. 7 and 12.

Over gently rolling desert land.

40.00

Point for the  $\frac{1}{4}$  sec. cor. of secs. 7 and 12.

Set an iron post, 3 ft. long, 1 in. diam., 28 ins. in the ground, with brass cap mkd.

$\frac{1}{4}$	
S12	S7
1947	

raise a mound of stone, 3 ft. base, 2 ft. high, W. of cor.

80.00

Point for the cor. of secs. 1, 6, 7 and 12.

Set an iron post, 3 ft. long, 2 ins. diam., 28 ins. in the ground, with brass cap mkd.

T30N

R25E	R26E
S1	S6
S12	S7
1947	

raise a mound of stone, 3 ft. base, 2 ft. high, W. of cor.

Land, gently rolling.

Soil, sandy.

Undergrowth, shadscale and sagebrush.

North, bet. secs. 1 and 6.

Over gently rolling desert.

24.00

Top of low sand hills, bears NE. and SW.; desc. gradual NW. slope.

32.70

Drain, course SW.

37.10

Main wash, course SW.

40.00

Point for the  $\frac{1}{4}$  sec. cor. of secs. 1 and 6.