

## INDEPENDENT RESURVEY OF THE NORTH BDY., T. 27 S., R. 62 E.

Chains

No timber.  
Undergrowth, creosote, black brush, cacti, bunch grass.  
Grazing, fair to good.

West, on a tangent line, bet. secs. 6 and 31, bearing S.89°56.2'W.

Over gentle rolling land through medium dense undergrowth.

31.20 Shallow wash, 20 lks. wide, course N.20°E.

40.00 N. 22 lks. from the tangent,

Set an iron post, 3 ft. long, 1 in. diam., 30 ins. in the ground, for  $\frac{1}{4}$  sec. cor., with brass cap mkd.

S31

$\frac{1}{4}$  ———

S 6

1940

raise a mound

of stone, 2 ft. base,  $1\frac{1}{2}$  ft. high, N. of cor.

From this cor., the original  $\frac{1}{4}$  sec. cor. bears N.68°45'W., 7.88 chs. dist., a basalt stone, 14x8x3 ins., mkd.  $\frac{1}{4}$  on W. face, firmly set in a mound of stone. I destroy all traces of this cor.

64.00 Shallow wash, 40 lks. wide, course N.30°E.

78.40 Wash, 60 lks. wide, 3 ft. deep, course N.10°E.

81.10 N. 26 lks. from the tangent,

Intersect the cor. of Ts. 26 and 27 S., Rs. 62 and 63 E..

Land, rolling.

Soil, gravelly to rocky, 3rd rate.

No timber.

Undergrowth, creosote, black brush, cacti, grasses.

Grazing, good.

## INDEPENDENT RESURVEY OF THE SUBDIVISION OF T. 27 S., R. 63 E.

Superseding the Survey Executed by Deputy Surveyor W.H. Myrick  
in May 1883 under Contract No. 145 dated July 11, 1882.

Prior to the reestablishment of the subdivisional corners, diligent search was made for the original corners. None of the original corners was found.

From the cor. of secs. 35 and 36 on the S. bdy. of the tp., which is an iron post, 2 ins. diam., set, mkd. and witnessed as described in the field notes of the resurvey of T. 28 S., R. 63 E.,

N.0°01'W., bet. secs. 35 and 36,

Over gentle rolling land through medium dense undergrowth.

40.00 Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for  $\frac{1}{4}$  sec. cor., with brass cap mkd.

$\frac{1}{4}$

S35 | S36

1940

raise a mound

of stone, 2 ft. base,  $1\frac{1}{2}$  ft. high, W. of cor.