

## Dependent Resurvey of a Portion of the Subdivision, T. 20 S., R. 60 E.

Chains

- 39.77 Point for the  $\frac{1}{4}$  sec. cor. of secs. 5 and 6, which is monumented with a wooden post, 4x4x36 ins. above ground, and mkd.  $\frac{1}{4}$  S on W. face; established by private engineer, but believed to be a perpetuation of the original cor. position.
- At the corner point
- Set an iron post, 30 ins. long, 2 $\frac{1}{2}$  ins. diam., 22 ins. in the ground, with brass cap mkd.
- T20S R60E  
S 6 | S 5  
1957
- Reset the wooden post alongside the iron post.
- N. 0° 05' E., beginning new measurement.
- 20.005 Point for the N. 1/16 sec. cor. of secs. 5 and 6, at proportionate dist.
- Set an iron post, 30 ins. long, 2 $\frac{1}{2}$  ins. diam., 20 ins. in the ground, and in a mound of stone, 2 ft. base, 10 ins. high, with brass cap mkd.
- T20S R60E  
N 1/16  
S 6 | S 5  
1957
- 40.16 The cor. of secs. 5, 6, 31 and 32 on the N. bdy. of the township, which is monumented with an iron post, 2 $\frac{1}{2}$  ins. diam., firmly set and mkd. as described in the official record.
- Land, nearly level desert valley.  
Soil, sandy and gravelly clay loam.  
Vegetation, yucca and creosote bush.
- 
- Subdivision of Section 4, T. 20 S., R. 60 E.
- 
- From the  $\frac{1}{4}$  sec. cor. of secs. 4 and 9.
- N. 0° 31' E., on N.-S. center line of sec. 4.
- Over desert valley land, along W. side of unimproved roadway, gradually entering same.
- 20.31 Point for the center S. 1/16 sec. cor. of sec. 4.
- Set an iron post, 30 ins. long, 2 $\frac{1}{2}$  ins. diam., 22 ins. in the ground, and in a mound of stone, 2 ft. base, 8 ins. high, with brass cap mkd.
- T20S R60E  
C  
S 1/16 | S 4  
C  
1957
- Corner is situated at intersection of E.-W. and N.-S. unimproved roadways.
- 40.62 Point for the center  $\frac{1}{4}$  sec. cor. of sec. 4, at intersection with E.-W. center line.