

306

Subdivision of Section 34, T. 22 S., R. 63 E.

Chains	
	Deposit broken glass 12 ins. below the surface of the ground, and raise a collar of stone around the iron post.
11.10	Wash, 15 lks. wide, 10 ins. deep, drains NW.
20.00	The Center-East Northeast 1/64 sec. cor.
	<p>From the South-North 1/64 sec. cor. of secs. 34 and 35.</p> <p>S. 89° 48' W., on the E-W center line of the SE$\frac{1}{4}$NE$\frac{1}{4}$.</p> <p>Over slightly rolling land, through medium heavy undergrowth.</p>
8.80	Wash, 10 lks. wide, 1 ft. deep, drains NW.
10.005	The Southeast-Northeast 1/64 sec. cor.
20.010	The Center-South Northeast 1/64 sec. cor.
	<p style="text-align: center;">GENERAL DESCRIPTION</p> <p>The general elevation of the portion of the township surveyed or resurveyed ranges from 1800 ft. in elevation in the north portion to 2400 ft. in the south portion.</p> <p>The north portion of the area is nearly level and slightly rolling desert land, and the southern portion is gently rolling land. The soil is a loose grained sandy and gravelly loam. There are no trees, but the entire area is covered with a medium and/or heavy growth of cacti, yucca, creosote bush and sagebrush, with a sparse growth of native grasses. The drainage is in a general north-northwest direction but there are no streams in the area.</p> <p>Access to the area is gained by U. S. Highway Nos. 466, 93 and 95, a two-lane oil surfaced road which enters the area near the $\frac{1}{4}$ sec. cor. of secs. 17 and 20 and bears S. 42° 20' E. on a continuous tangent through secs. 20, 21, 28, 27, 34 and 35, leaving the township near the position for the West 1/16 sec. cor. of secs. 2 and 35.</p> <p>There are no settlers living in the portion of the township being surveyed at the present time, but there is a possibility there will be a demand for the land when more water is developed as the land is fairly close to the city of Henderson, Nevada.</p> <p>The Los Angeles and Salt Lake Railroad (Boulder Branch), enters the area being surveyed about midpoint between the $\frac{1}{4}$ sec. cor. of secs. 19 and 20 and the cor. of secs. 17, 18, 19 and 20, traverses in a general southeast direction through secs. 20, 29, 28, 33 and 34, leaving the township near the East-East 1/64 sec. cor. of secs. 3 and 34.</p> <p>No evidence of any mineral was found during the progress of the survey.</p>