

Independent Resurvey of the Subdivision of T. 17 S., R. 63 E.

Chains

From this cor. the standard  $\frac{1}{4}$  sec. cor. on the S. bdy. of sec. 35, T. 16 S., R. 63 E., bears W. 16.07 chs. dist., an iron post, 1 in. diam., set, mkd. and witnessed as described in the official record.

The  $\frac{1}{4}$  sec. cor. on the N. bdy. of sec. 2, T. 18 S., R. 63 E., an iron post 1 in. diam., set, mkd. and witnessed as described in the official record, was remarked.

T17S R63E

S35

S 2

T18S

1958

From the closing cor. of secs. 2 and 3, T. 18 S., R. 63 E., an iron post, 3 ins. diam., set, mkd. and witnessed as described in the official record. In accordance with the special instructions this cor. was remarked.

T17S R63E

S34 | S35

S3 | S2

T18S

1958

N. 0° 01' W., bet. secs. 34 and 35.

Over rolling desert land, drains E.

12.40 Wash, 2 ft. deep, 50 lks. wide, drains N. 65° E.

16.00 Wash, 3 ft. deep, 50 lks. wide, drains E.

38.33 Point for the  $\frac{1}{4}$  sec. cor. of secs. 34 and 35.

Set an iron post, 30 ins. long, 2 $\frac{1}{2}$  ins. diam., 10 ins. in the ground to bedrock, in a mound of stone, 3 $\frac{1}{2}$  ft. base to top, with brass cap mkd.

T17S R63E

S34 | S35

1958

Cont. along gentle E. slope.

45.30 Wash, 4 ft. deep, 40 lks. wide, drains N. 70° E.

50.88 Wash, 4 ft. deep, 50 lks. wide, drains E. irregularly; desc. 10 ft. along E. slope.

67.20 Wash, 2 ft. deep, 30 lks. wide, drains E.

70.30 Bulldozed road, bears N. 80° E. and S. 80° W.; desc. 15 ft. along E. slope.

78.33 Intersect sectional correction line.

Set an iron post, 30 ins. long, 2 $\frac{1}{2}$  ins. diam., 22 ins. in the ground, with brass cap mkd.

T17S R63E

S27 | S26

S34 | S35

1958