

Dependent Resurvey, T. 24 N., R. 40 E.

11

Chains

Dependent Resurvey of a portion of Subdivisional Lines,
T. 24N., R. 40 E.

Reestablishment of the survey executed by D. H. Barker and J. H. Eaton, Deputy Surveyors, in 1876.

From the cor. of secs. 1, 2, 35 and 36, on the S. bdy. of the Tp.
N. 0° 36' E., bet. secs. 35 and 36.

Over gently rolling land.

6.00 Trail road, bears NW and S. 10° E.

14.00 Bulldozed road, bears NE and SW.

40.26 The $\frac{1}{4}$ sec. cor. of secs. 35 and 36, monumented by a granite stone,
15x7x4 ins., firmly set and properly mkd.

At the cor. point

Set an iron post, 30 ins. long, 2½ ins. diam., 24 ins. in the
ground, with brass cap mkd.

T24N R40E

$\frac{1}{4}$
S35 | S36

1960

Bury the original cornerstone alongside the iron post.

No available accessories.

N. 0° 37' E., beginning new measurement.

Over gently rolling land.

6.20 Small wash, drains NE.

39.20 Small wash, drains NW.

40.33 The cor. of secs. 25, 26, 35 and 36, monumented by a granite stone,
12x9x5 ins., firmly set and properly mkd.

At the cor. point

Set an iron post, 30 ins. long, 2½ ins. diam., 24 ins. in the
ground, with brass cap mkd.

T24N R40E

S26 | S25
S35 | S36

1960

Bury the original cornerstone alongside the iron post.

No available accessories.

Land, gently rolling.

Soil, sandy clay and gravelly.

Timber, none.

Undergrowth, shadscale and white sage.