

Dependent Resurvey, Portion of Subdivisional Lines, T. 25 N., R. 40 E.

Chains

N. 0° 17' E., bet. secs. 35 and 36.

Over nearly level land.

2.70 Trail road, bears SW and NE.

39.25 Point for the $\frac{1}{4}$ sec. cor. of secs. 25 and 36, at proportionate dist.; there is no remaining evidence of the original cor.

At the cor. point.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.

T25N R40E

$\frac{1}{4}$
S35 | S36
1960

No available accessories.

78.50 Point for the cor. of secs. 25, 26, 35 and 36, at proportionate dist.; latitudinally and at record dist. longitudinally from the E. bdy.; there is no remaining evidence of the original cor.

At the cor. point.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.

T25N R40E

~~S26~~ | S25
S35 | S36
1960

No available accessories.

Land, nearly level.

Soil, light sandy clay.

Timber, none.

Undergrowth, shadscale.

From the cor. of secs. 25, 30, 31 and 36, on the E. bdy. of the Tp., monumented with an iron post, $2\frac{1}{2}$ ins. diam., set, mkd. and witnessed as described in the field notes of the 1959 resurvey of T. 25 N., R. 41 E.

S. 88° 54' W., bet. secs. 25 and 36.

Over nearly level land.

4.70 Trail road, bears NE and SW.

39.90 Point for the $\frac{1}{4}$ sec. cor. of secs. 25 and 36, at proportionate dist.; there is no remaining evidence of the original cor.

At the cor. point

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.

T25N R40E

$\frac{1}{4}$ S25
S36
1960

No available accessories.