

Remonumentation of Corners, HES No. 44, in
T. 10 N., R. 42 E. (Unsurveyed)

Chains

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 26 ins. in the ground, over broken glass, and with orig. cor. stone buried on S. side of post; brass cap marked

8
HES44

1961

Place collar of rock around post.

Cor. is located at cor. of fences bearing S. and N. 78° E.

The point for cor. No. 9, HES No. 44, (cor. post missing) is re-established at its record position from one of the original bearing posts.

A cedar cor. fence post, firmly set, 9 ft. long, 8 ins. diam., scribed X 9 HES 44 BP, bears S. $69^{\circ} 45'$ W., 7 lks. dist.

There is no remaining evidence of the other bearing post recorded as being S. 15° W., 24 lks. dist.

At cor. point.

Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 26 ins. in the ground, over broken glass deposit; brass cap marked

9
HES44

1961

Place collar of rock around post.

Corner is located 7 lks. dist. from the NE. cor. of fences bearing S. $78\frac{1}{2}^{\circ}$ W., and S., and about 2 chs. dist. NE. of house.

Remonumentation of Corners, HES No. 83 in T. 9 N.,
R. 42 E. (Unsurveyed)

Homestead Entry Survey No. 83, located in unsurveyed sections 31 and 32, T. 9 N., R. 42 E., Mount Diablo Meridian, Nevada, was surveyed by W. B. Rice, Forest Assistant in 1914.

The following field notes are those of the remonumentation of identified original corners on Homestead Entry Survey No. 83, located in unsurveyed sec. 32, T. 9 N., R. 42 E., M.D. Mer., Nevada.

The corners remonumented were selected by the Forest Service as being adjacent to, or controlling the boundaries of Forest Service Lands. The remonumentation was requested by, and accomplished in cooperation with the Forest Service.