

Remonumentation of Corners, HES No. 139 in  
T. 10 N., R. 40 E., (Unsurveyed)

## Chains

Place collar of rock around; and rebuild mound of stone.

Located on E. slope, about  $\frac{1}{2}$  ch. dist. W. of ditch, drains S., and 75 lks. W. of corner of fences along S. and W. bdys. of claim.

At cor. No. 5, HES No. 139, monumented by a granite stone, 26x11x10 ins., firmly set, marked 5 HES 139 on side facing claim, and a cross on top (which I destroyed); witnessed by a mound of stone on the SE. side, and two bearing rocks, SW. and NW., as described in the official record.

At cor. point

Set an iron post, 30 ins. long,  $2\frac{1}{2}$  ins. diam., 24 ins. in the ground, over broken glass, with orig. cor. stone buried on W. side of post; brass cap marked

5  
HES  
139  
1961

Collar of rock around post, and rebuild the stone mound.

Corner located inside fence on cleared land - NW cor. of fences bears N. approximately  $72^\circ$  W., 70 lks. dist.

Road NS. bears W. from cor. about 80 lks. dist.

Remonumentation of Corners, HES No. 140, in  
T. 8 N., R. 41 E. (Unsurveyed)

Homestead Entry Survey No. 140, located in unsurveyed sec. 5, T. 8 N., R. 41 E., Mount Diablo Meridian, Nevada, was surveyed by F. C. Haman, Forest Ranger, in 1917.

The following field notes are those of a remonumentation of identified original corners on HES No. 140, in sec. 5, T. 8 N., R. 41 E., M.D. Mer. The position of each corner was marked by the original monument.

The corners remonumented were selected by the Forest Service as being adjacent to, or controlling the boundaries of Forest Service Lands. The remonumentation was requested by, and accomplished in cooperation with the Forest Service.

Homestead Entry Survey No. 140

Corner No. 1 HES No. 140 is marked by a cross cut into top of a granite boulder,  $2 \times 2 \times 1\frac{1}{2}$  ft., with marks 1 HES 140 on side facing claim; from which

A granite rock,  $3 \times 2 \times 1\frac{1}{2}$  ft., mkd. 1 HES 140 BR, bears S.  $59^\circ 35'$  E., 30 lks. dist.