

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FIELD NOTE PAPER

| CHAINS |   |
|--------|---|
| 61.40  | <p style="text-align: center;">T44N R31E<br/><math>\frac{1}{4}</math><br/>S 6   S 5<br/>1962</p> <p>Trail road, bears N. 70° E. and S. 70° W.</p>   |
| 82.52  | <p>The cor. of secs. 5, 6, 31 and 32, on the N. bdy. of the Tp.</p> <p>Land, rolling.<br/>Soil, sandy clay.<br/>Undergrowth, sagebrush, shadscale, buttonbrush and greasewood.</p> <p style="text-align: center;">GENERAL DESCRIPTION</p> <p>The land within this township is nearly level, with scattered washes draining generally South to SW. The soil is sandy clay throughout the township with sagebrush, shadscale, buttonbrush and undergrowth.</p> <p>The area has access roads throughout the Tp., with Highway 8A bearing S. 26° 45' E. and N. 26° 45' W., entering the SW. cor. of sec. 36 and leaving the Tp. in the NW. cor. of sec. 4</p> <p>The water in this Tp. comes from springs and one well. Two springs are located in the NE. cor. of sec. 4, another located in T. 44N., R. 30 E., with a pipe line running to a stock trough in the southern part of sec. 18. The well is in the northern part of sec. 35, just west of Highway 8A.</p> <p>There is no timber in the area and no mineral formations of consequence were noted during the survey.</p> |
|        |   |