UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FIELD NOTE PAPER

	CHAINS	DEPENDENT RESURVEY OF THE EAST BDY., T. 43 N., R. 31 E.
	,	Reestablishment of the Survey Executed by Skinner, Garside and Preble, Deputy Surveyors in 1873.
	,	The cor. of Tps., 42 and 43 N., R. 31 and 32 E., monumented with the original squared woodpost, 1x1x36 ins. long, there are no legible marks, loosely set.
	9	At the corner point
		Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. in diam., 24 ins. in the ground and in a collar of stone, with brass cap mkd.
	8	T43N R31E R32E S 36 S 31 S 1 S 6 T42N 1962
		Reset original woodpost alongside the iron post.
		N. 0° 56' E., bet. secs. 31 and 36.
		Over gently rolling land, through mediun undergrowth.
	40.28	Point for the ½ sec. cor. of secs. 31 and 36, at proportionate distance; there is no remaining evidence of the original corner.
		Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. in diam., 24 ins. in the ground and in a collar of stone, with brass cap mkd.
		T43N R31E R32E
	E. E.	S 36 S 31 1962
	51.20	R. E. A. powerline, bears N. 34° 24' E. and S. 34° 24' W.
	58.60	Trail road, bears N. 30° E. and S. 30° W.
	61.30	Fence, 5 strand barb-wire, bears SW. and NE., 2.00 chs., thence N.
	80.56	Point for the cor. of secs. 25, 30, 31 and 36, at proportionate distance; there is no remaining evidence of the original corner.
	*	Set an iron post, 30 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground and in a collar of stone, with brass cap mkd.
		T43N R31E R32E
5		S 25 S 30 S 36 S 31
		1962