

1422

## Dependent Resurvey of a portion of the N. Bdy. T. 8 N., R. 45 E.

Chains

Reestablishment of the portion of the N. Bdy.  
T. 8 N., R. 45 E., executed by Don H. Barker,  
Deputy Surveyor, in 1874.

Beginning at the cor. of Ts. 8 and 9 N., Rs. 45 and 46 E.  
marked by the 1931 resurvey monument, which is an iron  
post, 3 ins. diam., firmly set in the ground, mkd. and  
witnessed as described in the official record.

N. 89° 06' W., bet. secs. 1 and 36.

Over rolling mountainous land, through dense undergrowth;  
asc. gradually over an E. slope 80 ft. to  $\frac{1}{4}$  sec. cor.

- 3.90 Road, unimproved, bears N. and S.  
33.70 Wash, course NE.  
35.30 Road, unimproved, bears N. and S.  
39.98 The  $\frac{1}{4}$  sec. cor. of secs. 1 and 36, marked by the original  
monument, a sand stone, 4x6x10 ins., firmly set in the  
ground and in a small mound of stone, marked  $\frac{1}{4}$  on N.  
face.

At the corner point.

Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in  
the ground, with brass cap mkd.

S 36  
 $\frac{1}{4}$  ———  
S 1  
1939

Raise a mound of stone, 2 ft. base, 1 $\frac{1}{2}$  ft. high, N. of  
cor.  
Bury the original corner stone alongside the iron post.

N. 89° 31' W., beginning new measurement.

Asc. 40 ft. to wash.

- 4.60 Road, unimproved, bears N. 70° E. and S. 70° W.  
9.70 Wash, course S. 65° E.; leave rolling mountainous and  
enter mountainous land, bears N. and S.; asc. 30 ft.  
15.00 Enter scattering timber, bears N. and S.; asc. 40 ft.  
22.80 Road, unimproved, bears N. 70° W., and S. 70° E.; asc.  
35 ft.  
24.40 Wash, course S. 65° E.; asc. 370 ft. over a rocky E.  
slope.  
40.10 Point for the cor. of secs. 1, 2, 35 and 36, at propor-  
tionate distance; there is no remaining evidence of the  
original corner.  
Set an iron post, 3 ft. long, 2 ins. diam., 28 ins. in  
the ground, with brass cap mkd.