555 Chains N. 0° 02' W., on true line bet. secs. 2 and 3. Desc. 210 ft. over rolling mountainous land, along a W. slope, thru scattering undergrowth. Spur, slopes N. 60° W.; continue descent over a N. slope. 28.00 Set an iron post, 3 ft. long, 1 in. diam., 30 ins. in the ground, 40.00 with a quart of charcoal deposited at base, for the $\frac{1}{4}$ sec. cor., with brass cap mkd. 1940 No suitable accessory. Winding draw, drains W.; asc. 70 ft. over a S. slope. 42.10 Spur, slopes N. 60° W.; desc. 240 ft. over a N. slope. 49.50 Intersect the 8th standard parallel N. 80.84 Set an iron post, 3 ft. long, 2 ins. diam., 30 ins. in the ground, for the closing cor. of secs. 2 and 3, with brass cap mkd. T 41 N R 35 E T 40 N R 35 E raise a mound of stone, 2 ft. base, $1\frac{1}{2}$ ft. high, S. of cor. From this point the standard cor. of secs. 34 and 35, bears N. 88° 53' E., 6.62 chs. dist. Land, rolling mountainous. Soil, sandy, alkaline clay, 3d rate. No timber; undergrowth, sagebrush and shadscale. Grazing, fair. From the cor. of secs. 3, 4, 33 and 34, on the S. bdy. of the Tp., N. 0° 02' W., bet. secs. 33 and 34. Desc. slightly over rolling land, along a W. slope, thru scattering undergrowth. 12.80 Draw, drains N. 80° W. Draw, drains S. 70° W. 15.40 27.30 Draw, drains S. 70° W. 34.20 Road, bears N. 50° W. and S. 80° E. Set an iron post, 3 ft. long, 1 in. diam., 30 ins. in the ground, with a quart of charcoal deposited at base, for the $\frac{1}{4}$ sec. cor., 40.00 with brass cap mkd.