_		
	Chains	
		T4ON R35E S32 S33
		s 5 s 4
		T39N
		1940
	τ = 2	of stone, 2 ft. base, 12 ft. high, W. of cor.
		Land, rolling.
		Soil, sandy clay, 3d rate. No timber; undergrowth, sagebrush and shadscale.
		Grazing, poor.
		West, bet. secs. 5 and 32.
		Desc. 140 ft. over rolling land, on a W. slope, thru dense undergrowth.
	16.70	Wash, course N. 50° W.
	40.00	Set an iron post, 3 ft. long, 1 in. diam., 30 ins. in the ground, for $\frac{1}{4}$ sec. cor., with brass cap mkd.
		S 32
		S 32
1		s 5
		1940 raise a mound
		of stone, 2 ft. base, $1\frac{1}{2}$ ft. high, N. of cor.
-	80.00	Set an iron post, 3 ft. long, 2 ins. diam., 30 ins. in the ground, for cor. of secs. 5, 6, 31 and 32, with brass cap mkd.
		THON R35E
		S31 S32 S 6 S 5
		T39N
	0	1940
		of stone, 2 ft. base, $1\frac{1}{2}$ ft. high, W. of cor.
		Land, rolling.
2000		Soil, sandy, alkaline clay, 3d rate.
		No timber; undergrowth, sagebrush and shadscale. Grazing, poor.
	*	
		West, bet. secs. 6 and 31.
		Over rolling land, on a W. slope, thru scattering undergrowth.
	40.00	Set an iron post, 3 ft. long, 1 in. diam., 30 ins. in the ground, for \(\frac{1}{4} \) sec. cor., with brass cap mkd.
		s 31
		\$ 6
		1940
	40.	of stone, 2 ft. base, $1\frac{1}{2}$ ft. high, N. of cor.
	46.00	Road, bears NE. and SW.
	80.00	Set an iron post, 3 ft. long, 1 in. diam., 30 ins. in the ground, with a quart of charcoal deposited at base, for cor. of lots 4,
		5, 7 and 8, with brass cap mkd.