

East Boundary of T. 40 N., R. 34 E.

Chains

North, along the E. bdy. of sec. 13.

Over nearly level land, thru scattering undergrowth.

40.00

Set an iron post, 3 ft. long, 1 in. diam., 30 ins. in the ground, with a quart of charcoal deposited at base, for $\frac{1}{4}$ sec. cor., with brass cap mkd.
$$\frac{1}{4} S 13 \quad |$$

1940

No suitable accessory.

80.00

Set an iron post, 3 ft. long, 2 ins. diam., 30 ins. in the ground, with a quart of charcoal deposited at base, for cor. of secs. 12 and 13, with brass cap mkd.

T40N	T40N
S12	R35E
S13	
R34E	S7

1940

No suitable accessory.

Land, nearly level.

Soil, sandy, alkaline clay, 3d rate.

No timber; undergrowth, sagebrush and greasewood.

Grazing, poor.

North, along the E. bdy. of sec. 12.

Over nearly level land, thru scattering undergrowth.

40.00

Set an iron post, 3 ft. long, 1 in. diam., 30 ins. in the ground, with a quart of charcoal deposited at base, for $\frac{1}{4}$ sec. cor., with brass cap mkd.
$$\frac{1}{4} S 12 \quad |$$

1940

No suitable accessory.

80.00

Set an iron post, 3 ft. long, 2 ins. diam., 30 ins. in the ground, with a quart of charcoal deposited at base, for cor. of secs. 1 and 12, with brass cap mkd.

T40N	T40N
S 1	R35E
S12	
R34E	S6

1940

No suitable accessory.

Land, nearly level.

Soil, alkaline clay, 3d rate.

No timber; undergrowth, sagebrush and greasewood.

Grazing, fair.

North, along the E. bdy. of sec. 1.

Over nearly level land, thru scattering undergrowth.