Dependent Resurvey of the 8th Stan. Par. N. through R. 35 E. Chains At cor. point Set an iron post, 3 ft. long, 1 in. diam., 30 ins. in the ground, with the original cor. deposited at base, for standard $\frac{1}{4}$ sec. cor., with brass cap mkd. s c 1/4 s 32 No suitable accessory. Thence S. 88° 45' W. along the S. bdy. of sec. 32. 40.33 The original standard cor. of secs. 31 and 32; a cedar post, 1 in. sq., 12 ins. above ground, mkd. XXV, with other marks illegible, witnessed by pits and a mound of earth. At cor. point Set an iron post, 3 ft. long, 2 ins. diam., 30 ins. in the ground, with the original cor. deposited at base, for standard cor. of secs. 31 and 32, with brass cap mkd. SC TLIN R35E S31 S32 1940 No suitable accessory. Land, nearly level. Soil, sandy alkaline clay, 3d rate. No timber; undergrowth, shadscale and greasewood. Grazing, poor. S. 88° 52' W., along the S. bdy. of sec. 31. Over nearly level land, thru scattering undergrowth. 40.10 The original standard $\frac{1}{4}$ sec. cor.; a cedar post, 1 in. sq., 32 ins. above ground, with scribe marks illegible, and set in a mound of earth, with pits, E. and W. At cor. point Set an iron post, 3 ft. long, 1 in. diem., 30 ins. in the ground, with the original cor. post deposited alongside, for standard $\frac{1}{4}$ sec. cor., with brass cap mkd. S C \frac{1}{4} S 31 1940

No suitable accessory.

Thence

S. 88° 46' W., along the S. bdy. of sec. 31.

40.21 The original standard cor. of Tps. 41 N., Rs. 34 and 35 M.; a cedar post, 1 in. sq., 3 ins. above ground, broken, with remainder upon a mound of earth, badly weather worn, with illegible scribe marks.