

T. 9 $\frac{1}{2}$ N., R. 71 E.

Chains

From point of intersection, the $\frac{1}{4}$ sec. cor. on the S. bdy. of sec. 36, T10N R70E., bears West, 48.90 chs. dist., an iron post, 1 in. diam., firmly set and mkd. as described in the official record. This corner was changed to refer to the one section only and the brass cap is now mkd.

$$\frac{1}{4}$$

$$\underline{S36}$$

1915

From point of intersection, the closing cor. of T. 10 N., R. 70 E., identical with closing cor. of T. 9 $\frac{1}{2}$ N., R. 71 E., on the Nevada-Utah state boundary bears East 69.97 chs. dist.

Land, slightly rolling.

Soil, gravelly clay; 3rd rate.

Timber, none.

Undergrowth, yellowtop, white sage, shadscale and stunted black sage.

Grazing, fair.

On the S. bdy. of Sec. 36, T. 10 N., R. 70 E., at a point East 40.00 chs. dist. from the closing cor. of fractional Tps. 9 $\frac{1}{2}$ N., Rs. 70 and 71 E.,

Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, with a pint clear glass bottle deposited at base, for $\frac{1}{4}$ sec. cor., on the N. bdy. of fractional sec. 31, with brass cap mkd.

$$\frac{1}{4}$$

$$\underline{S31}$$

1915

of stone, 2 ft. base, 1 $\frac{1}{2}$ ft. high, S. of cor. raise a mound

GENERAL DESCRIPTION

Fractional T. 9 $\frac{1}{2}$ N., R. 71 E. is located on the "bench" on the E. side of Hamlin Valley, on a very gradual general W. slope. The soil is a relatively shallow gravelly clay of approximately 3rd rate, which supports a fairly good stand of white sage, shadscale and a low black sage, the yearly new growth of which furnishes fairly good winter feed for livestock. An unimproved road passes through the Tp. in a N. and S. direction. There is no timber within the township. There is no source of water within the Township, the use for grazing depending upon snowfall in the winter for water.