

W. BDY. T. 46 N., R. 28 E.

Chains

- 62.00 Enter flat grassy bottom land, bears E. and W.
- 74.40 Draw, drains S. 40° E.
- 80.00 Point for cor. of secs. 1, 6, 7 and 12, at proportionate position; there is no remaining evidence of the original corner.

Corner not reestablished.

Land, mostly rolling.
Soil, sandy, 2nd rate.
No timber; undergrowth, sagebrush and shadscale.
Grazing, poor.

N. 0° 38' E., bet. secs. 1 and 6.

Over low, gently rolling land, through medium dense sagebrush and greasewood.

- 40.00 Point for the $\frac{1}{4}$ sec. cor. of secs. 1 and 6, at proportionate position; there is no remaining evidence of the original corner.

Corner not reestablished.

- 80.00 Point for the cor. of Ts. 46 and 47 N., Rs. 27 and 28 E., at proportionate position, which is record distance North from the standard cor. of Ts. 46 N., Rs. 27 and 28 E. and record distance West from the original corner of secs. 4, 5, 32 and 33, Ts. 46 and 47 N., R. 28 E.. There is no remaining evidence of the original corner.

Corner not reestablished.

Land, low and gently rolling.
Soil, part sandy, part alkaline, 2nd and 3rd rate.
No timber; undergrowth, greasewood and sagebrush.
Grazing, fair.

Portion of the N. Bdy. of T. 46 N., R. 28 E.

Retracement and Partial Reestablishment of the
Survey Executed by Hatch, Skinner and Trimble.
U.S. Deputy Surveyors, in 1874.

From the proportionate point for the cor. of Ts. 46 and 47 N.,
Rs. 27 and 28 E. (Corner not reestablished).

N. 85° 52' E., bet. secs. 6 and 31.

Over rolling land, through medium dense greasewood and sagebrush.

- 39.45 Point for the $\frac{1}{4}$ sec. cor. of secs. 6 and 31, at proportionate position; there is no remaining evidence of the original corner.

Corner not reestablished.

- 79.56 Point for cor. of secs. 5, 6, 31 and 32, at proportionate position; there is no remaining evidence of the original corner.

Corner not reestablished.

Land, low rolling hills.
Soil, sandy, 2nd rate.
Timber, none; undergrowth, sagebrush and greasewood.
Grazing, poor.