

Dependent Resurvey of the East Boundary of  
T. 34 N., R. 62 E.

19

Chains

T34N	
R62E	R63E
S24	S19
S25	S30
1942	

No suitable accessory.

Land, nearly level.  
Soil, clay; 3rd rate.  
No timber.  
Undergrowth, greasewood, rabbitbrush, rye grass.  
Grazing, good.

S. 1° 02' E., bet. secs. 25 and 30.

Over nearly level land, with many low sand dunes and numerous dry beds of small seasonal ponds.

40.00 The original meander  $\frac{1}{4}$  sec. cor., a juniper stake,  $1\frac{1}{2}$  ins. diam., 20 ins. long, badly weathered and cracked.

At point for corner

Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, with a quartzite stone, 2x6x10 ins., mkd. with a cross (X), deposited at base, and the original post alongside, for meander  $\frac{1}{4}$  sec. cor., with brass cap mkd.

T34N	
R62E	R63E
$\frac{1}{4}$	
S25	S30
MC	

1942

No suitable accessory.

Land, nearly level and slightly rolling.  
Soil, clay; 4th rate.  
No timber.  
Undergrowth, greasewood and shadscale.  
Grazing, poor.

Dependent Resurvey of the Subdivision of  
T. 34 N., R. 62 E.

Reestablishment of surveys executed by  
Hatch and Eaton, Deputy Surveyors in  
1870

From the cor. of secs. 19, 24, 25 and 30, on the E. bdy. of the township.

N. 89° 21' W., bet. secs. 24 and 25. (E.  $\frac{1}{2}$  mile.)

Across greasewood and salt grass flat.