Dependent Resurvey of the East Boundary of T. 35 N., R. 62 E.

Chains

N. 0° 28' W., bet. secs. 1 and 6.

 $(N_{\bullet} \stackrel{1}{\geq} mile_{\bullet})$

Over slightly rolling land.

6.00

Unimproved road, bears S. $77\frac{1}{2}^{\circ}$ E. and N. $77\frac{1}{2}^{\circ}$ W.

40.80

Intersect the Seventh Standard Parallel North at the original closing township corner of Tps. 35 N., Rs. 62 and 63 E., a very old cottonwood post, 2 ins. diam., 36 ins. long, badly weathered and rotted, fallen on a mound of earth, beside a more recently set stake.

At point for corner

Set an iron post, 3 ft. long, 3 ins. diam., 27 ins. in the ground, with a granite stone, \(\frac{1}{2}\times 8\times 10\) ins., mkd. with a cross (X), deposited at base, and the original post alongside, for closing corner of Tps. 35 N., Rs. 62 and 63 E., with brass cap mkd.

1943

No suitable accessory.

From this closing corner, the standard cor. of Tps. 36 N., Rs. 62 and 63 E., an iron post, 3 ins. diam., set, mkd. and witnessed as described in the official record, bears S. 89° 46' E., 20.62 chs. dist.

From this closing corner, the standard $\frac{1}{4}$ sec. cor. of sec. 36, an iron post, 1 in. diam., set, mkd. and witnessed as described in the official record, bears N. 89° 46' W., 19.55 chs. dist.

Land, slightly rolling. Soil, gravelly clay; 3rd rate. No timber; undergrowth, sagebrush. Grazing, fair.

Dependent Resurvey of the Subdivision of T. 35 N., R. 62 E.

Reestablishment of surveys executed by Hatch and Eaton, Deputy Surveyors, in 1870.

From the cor. of secs. 1, 2, 35 and 36, on the S. bdy. of the township, an iron post, 2 ins. diam., described in the field notes of the dependent resurvey of T. 34 N., R. 62 E., executed under this same group.

N. 0° 17' W., bet. secs. 35 and 36.

Over nearly level land.

40.03

Proportionate point.

Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, with charcoal deposited at base, for $\frac{1}{4}$ sec. cor., with brass cap mkd.