

DEPENDENT RESURVEY OF A PORTION OF S. BDY. T. 17 S., R. 50 E.

CHAINS

Land, nearly level to slightly rolling.
Soil, sandy and gravelly clay loam.
Timber, none; undergrowth, creosote bush and greasewood.

N. 89° 21' W., bet. secs. 5 and 32.

Over slightly rolling land, through scattering timber and undergrowth.

36.40 Carson Slough, running water, 50 lks. wide, 2 ft. deep, course S.

40.16 Point for the $\frac{1}{4}$ sec. cor. of secs. 5 and 32, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.

T17S R50E

$\frac{1}{4}$ $\frac{S \ 32}{S \ 5}$

T18S

1963

deposit broken glass around the iron post, 6 ins. below the surface of the ground.

42.00 Leave scattering timber, edge bears NNE. and SSW.

49.90 Road, bulldozed, bears N. and S. 10° W.

80.31 The cor. of secs. 5, 6, 31 and 32, monumented with an iron post, 2 ins. diam., firmly set in the ground, mkd. and witnessed as described in the official record.

Land, slightly rolling.
Soil, sandy and gravelly clay loam.
Timber, mesquite and cottonwood.
Undergrowth, sagebrush, greasewood and creosote bush.

DEPENDENT RESURVEY OF A PORTION OF THE W. BDY. ,
T. 17 S., R. 50 E., MDM, NEVADA

Re-establishment of a portion of the survey
executed by E. A. Carter, Deputy Surveyor, in
1881, and a portion retraced by Yundt and Wilson
in 1934

From the cor. of secs. 25, 30, 31 and 36, on the W. Bdy.
of T. 17 S., R. 50 E., monumented with an iron post, 2 ins.
diam., firmly set in the ground, mkd. and witnessed as
described in the official record.

N. 1° 43' W., bet. secs. 25 and 30.

Over slightly rolling land, through scattering undergrowth.

39.28 Point for the $\frac{1}{4}$ sec. cor. of secs. 25, and 30, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.