

## SURVEY OF THE SUBDIVISION, T. 32 N., R. 34½ E.

## CHAINS

From this same corner, the ¼ sec. cor. of sec. 17, T. 32 N., R. 35 E., bears S. 0° 30' W., 34.17 chs. dist., heretofore described.

The point for the E. ¼ sec. cor. of sec. 1, at a point EAST of the W. ¼ sec. cor. of sec. 1 and on the W. bdy. of sec. 8, T. 32 N., R. 35 E.

Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.

T32N  
R34½E R35E  
¼  
S 1

1967

set a steel fence post, 5½ ft. long, 2½ ft. in the ground, alongside the iron post.

From this corner, the cor. of secs. 5 and 8, T. 32 N., R. 35 E., bears N. 0° 54' E., 5.335 chs. dist., heretofore described.

From this same corner, the W. ¼ sec. cor. of sec. 8, T. 32 N., R. 35 E., bears S. 0° 54' W., 34.585 chs. dist., heretofore described.

## GENERAL DESCRIPTION

The land within Township 32 North, Range 34½ East, is nearly level in the north and west portions; the southeast portion is mountainous. The elevation ranges from about 4,200 to 4,650 ft. above sea level. The soil varies from sandy loam in the lower elevations to sandy loam and rocky in the mountains. The vegetation consists of shadscale, greasewood, budsage and sagebrush. There is no timber.

No mineral formations of consequence were noted during the survey.

Principal users of the area are cattlemen. Access into the township is provided by Interstate highway No. 80, which runs through section 1, and trail roads.