DEPENDENT RESURVEY OF THE SUBDIVISIONAL LINES, T. 38 N., R. 44 E.

	T. 38 N., R. 44 E.
CHAINS	T007 7/47
	T38N R44E S 26 S 25
	S 35 S 36
	1971
	reset the steel fence post and the wooden post alongside the iron post and raise a mound of stone, 4 ft. base, 3 ft. high, W. of cor.
	From the cor. of secs. 25, 30, 31 and 36, on the E. bdy. of the Tp., monumented with an iron post, $2\frac{1}{2}$ ins. diam., set, mkd. and witnessed as described in the field notes of the 1970 resurvey of T. 38 N., R. 45 E.
	N. 86° 42' W., bet. secs. 25 and 36.
	Over nearly level land, through medium greasewood and sagebrush.
25.00	Ditch, 20 lks. wide, 1 ft. deep, drains SW.
25.30	Evans Creek, dry, 20 1ks. wide, 1 ft. deep, course SW.
41.38	Point for the ½ sec. cor. of secs. 25 and 36, at proportionate distance; there is no remaining evidence of the original corner.
	Set an iron post, 28 ins. long, 2½ ins. diam., 22 ins. in the ground, with brass cap mkd.
,	T38N R44E S 25 S 36
	1971
	raise a mound of stone, 3 ft. base, 2 ft. high, N. of cor.
45.00	Graded road, bears N. 9° E. and S. 9° W.
63.90	Fence, bears N. 46° E. and S. 46° W.
82.76	The cor. of secs. 25, 26, 35 and 36.
	N. 0° 40' E., bet. secs. 25 and 26.
	Over nearly level land, through medium greasewood and sagebrush.
40.16	The ½ sec. cor. of secs. 25 and 26, monumented with a steel fence post, extending 4 ft. above the ground, with an unmarked squared wooden post, 2x2x20 ins., attached to the fence post.
	At the corner point