

DEPENDENT RESURVEY OF THE SUBDIVISIONAL LINES,  
T. 38 N., R. 44 E.

CHAINS	
26.30	Telephone line, parallels graded road.
39.92	The cor. of secs. 29, 30, 31 and 32.
	N. 89° 36' W., bet. secs. 30 and 31.
	Over nearly level land, through sagebrush.
23.60	Trail road, bears N. and S.
40.04	The $\frac{1}{4}$ sec. cor. of secs. 30 and 31, monumented with a steel fence post, extending 4 ft. above ground, with an unmarked squared wooden post, 2x4x30 ins., attached to the steel fence post.
	At the corner point
	Set an iron post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.
	$\begin{array}{r} T38N R44E \\ S 30 \\ \frac{1}{4} \\ S 31 \end{array}$
	1971
	reset the steel fence post and wooden post alongside the iron post and raise a mound of stone, 4 ft. base, 3 ft. high, N. of cor.
	N. 89° 39' W., beginning new measurement.
	Over nearly level land.
40.28	The cor. of secs. 25, 30, 31 and 36, on the W. bdy. of the Tp., monumented with an iron post, 2 $\frac{1}{2}$ ins. diam., set, mkd. and witnessed as described in the official record.
	The W. $\frac{1}{4}$ sec. cor. of sec. 31, T. 38 N., R. 44 E., is determined to be identical with the E. $\frac{1}{4}$ sec. cor. of sec. 36, T. 38 N., R. 43 E., as this position is harmoniously related to the monuments found at the $\frac{1}{4}$ sec. cors. of secs. 31 and 32, at 33 and 34, and at 35 and 36 of T. 38 N., R. 44 E. The corner is monumented with an iron post, 2 $\frac{1}{2}$ ins. diam., set, mkd. and witnessed as described in the official record. I remark the brass cap as follows:
	$\begin{array}{r} T38N \\ R43E R44E \\ \frac{1}{4} \\ S 36   S 31 \end{array}$
	1963