

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES,  
T. 45 N., R. 61 E., MDM, NEVADA

## CHAINS

39.39

The  $\frac{1}{4}$  sec. cor. of secs. 10 and 15, monumented with a mound of stone. No mkd. stone found. This position is harmoniously related to other existing corners found, and is accepted as the best available evidence of the original corner position.

At the corner point

Set an iron post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 14 ins. in the ground to bedrock and in a mound of stone, 4 ft. base to top, with brass cap mkd.

T45N R61E  
S 10  
 $\frac{1}{4}$  S 15

1972

set a steel fence post, 6 ft. long, 14 ins. in the ground, alongside the iron post.

S.  $89^{\circ} 54'$  W., beginning new measurement.

Ascend 250 ft. over broken E. slope.

14.00 Ridge, bears NNW. and SSE.; desc. 120 ft. over W. slope.

28.30 Draw, drains S.; asc. 120 ft. over E. slope.

35.00 Spur, projects S.; desc. gradually over W. slope.

39.52 The cor. of secs. 9, 10, 15 and 16.

GENERAL DESCRIPTION

The area contained in this survey varies from level bottom land to mountainous. The elevation ranges from 5,700 to 6,300 ft. above sea level. The soil varies from sandy loam along the creek bottoms, to extremely rocky in the higher elevations. The vegetation in the higher elevations consists of sagebrush and reseeded grasses. There is medium to dense patches of willows along the creek bottoms.

The South Fork of Salmon Falls Creek flows in a north-easterly direction through the southeast portion of sec. 25. Canyon Creek flows in a southeasterly direction through secs. 15, 14, 23 and 24. Pole Creek flows south-easterly through sec. 15 to confluence with Canyon Creek.

The Home Ranch (formerly the O'Neil Ranch) headquarters is situated in the northeast portion of sec. 24. The bottom land along Canyon Creek and Salmon Falls Creek is used by this ranch for the production of hay. The remainder of the area is used for grazing.

Access to the area is available by means of a well maintained gravel road and several trail roads.

There was no mining activity noted in the area.